LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50 37429 - Hydraulic System

Sample No: LH0277647
Oil Type: NOT GIVEN



CONTAMINATION							
Particles >4µm		3610					
Particles >6µm		975					
Particles >14μm		57					
ISO 4406:1999 (c)		19/17/13					
Silicon	ppm	() <1					
Sodium	ppm	0 <1			***		
Potassium	ppm	0 <1					

WEA	R METALS			
Iron	ppm	4	 	
Copper	ppm	1	 	
Lead	ppm	0 <1	 	
Tin	ppm	0	 	
Aluminum	ppm	0 <1	 	
Chromium	ppm	0 <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0 <1	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	206				
Magnesium	ppm	<1				
Zinc	ppm	756				
Phosphorus	ppm	580				
Barium	ppm	<1				
Boron	ppm	<1				





LIEBHERR CANADA LTD. 1015 SUTTON DRIVE BURLINGTON, ON

CA L7L 5Z8

Contact: Joseph Rodgers joseph.rodgers@liebherr.com

T: (905)319-9222 F: (905)319-6622

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5657998Signed:Wes DavisReport Date:16 Oct 2023

CONSTRUCTION EQUIPMENT





GRAPHS

