LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 121164-1216 - Transmission (Manual)

Sample No: LH

Oil Type: PETRO CANADA 10W40

SAMPLEIN	IFORMATION			
Sample Number	LH	LH0235219	LH	LH0177775
Sample Date	02 Oct 2023	08 Nov 2022	04 Oct 2021	06 Oct 2020
Machine Hours	4259	3298	0	0
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL
OIL CONDI	TION			

OIL CO	ONDITION				
Visc @ 40°C	cSt	58.0	56.9	O 52.7	

CONTAMINATION							
Silicon	ppm	3	3	3	3		
Sodium	ppm	11	16	○ 28	○ 34		
Potassium	ppm	0 <1	1	3	3		

WEA	R METALS				
Iron	ppm	12	O 14	O 16	O 10
Copper	ppm	20	O 27	○ 38	○ 21
Lead	ppm	1	O 1	2	1
Tin	ppm	○ <1	O <1	1	 <1
Aluminum	ppm	4	4	6	5
Chromium	ppm	0	0	O <1	O <1
Molybdenum	ppm	50	○ 38	18	O <1
Nickel	ppm	0	O <1	0	O <1
Titanium	ppm	0	<1	0	<1
Silver	ppm	○ <1	0	O <1	0
Manganese	ppm	4	6	1 1	14
Vanadium	ppm	0	0	<1	<1

variaululli	ppiii	U	U	< I	< I	
ADD	ITIVES					
Calcium	ppm	1630	O 1910	○ 2709	○ 3284	
Magnesium	ppm	775	O 616	292	7	
Zinc	ppm	1213	O 1172	O 1202	O 1125	
Phosphorus	ppm	1096	O 1159	O 1158	O 1058	
Barium	ppm	<1	O <1	O <1	1	
Boron	ppm	2	O 2	3	3	



ACIER CENTURY INC 600 BERGE DU CANAL LACHINE, QC CA H8R 1H4 Contact: SERVICE

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. Viscosity of sample indicates oil is within SAE 20 range, advise investigate. The condition of the fluid is acceptable for the time in service.

Depot: ACILAC
Unique No: 5658428
Signed: Kevin Marson
Report Date: 16 Oct 2023

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

