LIEBHERR

CONSTRUCTION EQUIPMENT



Sample No: LH0274762

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

_						
SAMPLEINFORMATION						
Sample Number	LH0274762					
Sample Date	13 Oct 2023					
Machine Hours	25204					
Oil Hours	0					
Oil Changed	N/A					
Sample Status	ABNORMAL					

0	OIL CC	NDITION			
Visc @	40°C	cSt	101	 	

CON	NTAMINA	ATION		
Water	%	NEG	 	
Silicon	ppm	2	 	
Sodium	ppm	 <1	 	
Potassium	ppm	0	 	

WE!	AR META	16		
VV EA	AK ME I A			
Iron	ppm	18	 	
Copper	ppm	O 60	 	
Lead	ppm	2	 	
Tin	ppm	3	 	
Aluminum	ppm	0	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

ADDITIVES							
Calcium	ppm	10					
Magnesium	ppm	1					
Zinc	ppm	10					
Phosphorus	ppm	1219					
Barium	ppm	() <1					
Boron	ppm	307					



HIGGS & HIGGS RR # 4 ST THOMAS, ON CA N5P 3S8 Contact: Bernie Higgs

T: (519)631-4095 F: (519)631-2745

Diagnosis

We recommend that you drain the oil from the component if this has not already been done. We recommend an early resample to monitor this condition. Copper ppm levels are abnormal. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot: HIGSTT
Unique No: 5658786
Signed: Kevin Marson
Report Date: 18 Oct 2023

LIEBHERR







GRAPHS

