CONSTRUCTION EQUIPMENT

[[575873]] LIEBHERR HS8100 184908 - 2 Winch

Sample No: LH0277704

PETRO CANADA TRAXON 75W90 SYNTHETIC Oil Type:

Sample Information						
Sample Number	LH0277704	LH0251530	LH0230697			
Sample Date	12 Oct 2023	23 Jan 2023	22 Jul 2022			
Machine Hours	12289	10946	10063			
Oil Hours	0	0	0			
Oil Changed	N/A	Changed	N/A			
Sample Status	ABNORMAL	SEVERE	NORMAL			

nber	LH0277704	LH0251530	LH0230697	
е	12 Oct 2023	23 Jan 2023	22 Jul 2022	***
urs	12289	10946	10063	
	0	0	0	
i	N/A	Changed	N/A	
tus	ABNORMAL	SEVERE	NORMAL	

0	Oil Co	ndition				
Visc @	40°C	cSt	95.3	97.0	70.8	
-4						

Contamination							
Water	%	NEG	NEG	NEG			
Silicon	ppm	O <1	O 11	O <1			
Sodium	ppm	1	O <1	O <1			
Potassium	ppm	0	0	0			

Wed	ar Metals				
PQ			0		
Iron	ppm	32	1 961	7	
Copper	ppm	3	47	3	
Lead	ppm	 <1	O 2	O <1	
Tin	ppm	0	0	0	
Aluminum	ppm	0	O <1	O 0	
Chromium	ppm	0	2 6	0	
Molybdenum	ppm	0	O 1	0	
Nickel	ppm	 <1	9	<1	
Titanium	ppm	0	0	0	
Silver	ppm	<1	0	0	
Manganese	ppm	0	O 14	0	
Vanadium	ppm	0	<1	0	

Additives								
Calcium	ppm	12	25	66				
Magnesium	ppm	2	O <1	2				
Zinc	ppm	79	6 7	255				
Phosphorus	ppm	926	1303	980				
Barium	ppm	0 <1	O 0	0				
Boron	ppm	97	255	183				



Tillsonburg Ready-Mix Inc. 10 Elm Street Tillsonburg, ON **CA N4G 0A7**

Contact: Service Manager

T: F:

Diagnosis

We advise that you check for the source of water entry. We advise that you follow the water drain-off procedure for this component. We recommend an early resample to monitor this condition.All component wear rates are normal. Free water present. The oil is no longer serviceable due to the presence of contaminants.

Depot: TIL10TIL Unique No: 5658801 Signed: Kevin Marson Report Date: 18 Oct 2023





Graphs

