LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 139284-1253 - Front Differential

Sample No: LH0239950

Oil Type: LIEBHERR GEAR BASIC 90 LS

_					
U SAN	IPLE INFO	RMATION			
Sample Number		LH0239950	LH0241857	LH0241857	
Sample Date		04 Sep 2023	07 Jun 2023	18 Apr 2023	
Machine Hours		2265	1668	1142	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	N/A	
Sample Status		NORMAL	NORMAL	NORMAL	
<u> </u>					
OIL	CONDITIO	N			
Visc @ 40°C	cSt	179	O 188	92.7	
44					
CON	TAMINA1	TION			
Silicon	ppm	() <1	O 2	O <1	
Sodium	ppm	01	01	0 <1	
Potassium	ppm	0	00	0 <1	
	ррш	0	0 0	0 <1	
₩E/	AR METAL	S			
Iron	ppm	5	6	3	
Copper	ppm	○ <1	O <1	O <1	
Lead	ppm	0 <1	O 0	O 0	
Tin	ppm	0	O 0	O 0	
Aluminum	ppm	0 0	O <1	O 0	
Chromium	ppm	0	O 0	O 0	
Molybdenum	ppm	0	0	O 0	
Nickel	ppm	0 <1	O <1	O 0	
Titanium	ppm	0	0	0	
Silver	ppm	<1	0	0	
Manganese	ppm	0	O <1	O <1	
Vanadium	ppm	0	0	0	
ADD	ITIVES				
Calcium	ppm	8	O 20	6 5	
Magnesium	ppm	0	O 1	0	
Zinc	ppm	6	10	77	
Phosphorus	ppm	2290	○ 2391	O 1074	
Barium	ppm	 <1	O 0	O 0	
Boron	ppm	2	O 7	140	



HUBERT & FILS 474 ROUTE 105 BOIS-FRANC, QC CA J9E 3A9 Contact: Eric Brisebois ericbrisebois99@gmail.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:HUBBOIUnique No:5659441Signed:Wes DavisReport Date:19 Oct 2023





GRAPHS

