

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR A904 056759-005 - Rear Right Wheel Hub

Sample No: LH

Oil Type: GEAR OIL SAE 80



LIEBHERR CANADA LTEE
 444 AVENUE DE LA FRICHE
 DOLBEAU-MISTASSINI, QC
 CA G8L 3M7
 Contact: Luc Trottier
 luc.trottier@liebherr.com
 T:
 F: (418)276-9844



SAMPLE INFORMATION

Sample Number	LH	---	---	---
Sample Date	18 Oct 2023	---	---	---
Machine Hours	14788	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	82.9	---	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Silicon	ppm	1	---	---	---
Sodium	ppm	2	---	---	---
Potassium	ppm	0	---	---	---



WEAR METALS

Iron	ppm	13	---	---	---
Copper	ppm	4	---	---	---
Lead	ppm	0	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	<1	---	---	---
Chromium	ppm	0	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	139	---	---	---
Magnesium	ppm	3	---	---	---
Zinc	ppm	116	---	---	---
Phosphorus	ppm	1225	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	195	---	---	---

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80. Please confirm. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LBADOL
 Unique No: 5668908
 Signed: Wes Davis
 Report Date: 25 Oct 2023



GRAPHS

