

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### [MODERN] LIEBHERR L586 74609 - Front Left Wheel Hub

Sample No: LH0277037

Oil Type: LIEBHERR GEAR BASIC 90 LS



#### SAMPLE INFORMATION

Sample Number	LH0277037	---	---	---
Sample Date	21 Oct 2023	---	---	---
Machine Hours	1117	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

#### LIEBHERR CANADA

10 LYNDS AVENUE

MONCTON, NB

CA E1H 3K2

Contact: Mike Clark

Mike.Clark@liebherr.com

T: (506)854-2920

F: (506)854-2940



#### OIL CONDITION

Visc @ 40°C	cSt	189	---	---	---
-------------	-----	-----	-----	-----	-----



#### CONTAMINATION

Silicon	ppm	33	---	---	---
Sodium	ppm	10	---	---	---
Potassium	ppm	<1	---	---	---



#### WEAR METALS

Iron	ppm	645	---	---	---
Copper	ppm	144	---	---	---
Lead	ppm	4	---	---	---
Tin	ppm	12	---	---	---
Aluminum	ppm	2	---	---	---
Chromium	ppm	4	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	<1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	35	---	---	---
Vanadium	ppm	0	---	---	---



#### ADDITIVES

Calcium	ppm	13	---	---	---
Magnesium	ppm	6	---	---	---
Zinc	ppm	104	---	---	---
Phosphorus	ppm	2264	---	---	---
Barium	ppm	<1	---	---	---
Boron	ppm	4	---	---	---

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Viscosity of sample indicates oil is within SAE 90 range, advise investigate. The condition of the oil is acceptable for the time in service.

Depot: LIEMON

Unique No: 5669280

Signed: Kevin Marson

Report Date: 27 Oct 2023



### GRAPHS

