

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH50M 142911-1216 - Front Right Wheel Hub

Sample No: LH0246036

Oil Type: MOBIL MOBILUBE HD 80W90



Scierie Landrienne

Div. Les Chantiers Chibougamau, 389 Chemin du Moulin
Landrienne, QC
CA J0Y 1V0
Contact: Jason Boisvert
jason.boisvert@scierielandrienne.com
T: (819)732-2876
F:



SAMPLE INFORMATION

Sample Number	LH0246036	LH0246012	LH0246000	---
Sample Date	03 Nov 2023	09 Jun 2023	14 Apr 2023	---
Machine Hours	4990	3030	2050	---
Oil Hours	0	0	0	---
Oil Changed	Changed	Changed	Changed	---
Sample Status	NORMAL	NORMAL	NORMAL	---



OIL CONDITION

Visc @ 40°C	cSt	138	143	151	---
-------------	-----	-----	-----	-----	-----



CONTAMINATION

Silicon	ppm	9	13	56	---
Sodium	ppm	3	5	4	---
Potassium	ppm	0	<1	2	---



WEAR METALS

Iron	ppm	150	138	158	---
Copper	ppm	35	25	29	---
Lead	ppm	1	<1	<1	---
Tin	ppm	0	0	0	---
Aluminum	ppm	1	1	4	---
Chromium	ppm	<1	<1	<1	---
Molybdenum	ppm	0	<1	2	---
Nickel	ppm	<1	<1	0	---
Titanium	ppm	0	0	<1	---
Silver	ppm	<1	0	0	---
Manganese	ppm	2	3	5	---
Vanadium	ppm	0	0	0	---



ADDITIVES

Calcium	ppm	21	61	134	---
Magnesium	ppm	<1	1	2	---
Zinc	ppm	43	33	60	---
Phosphorus	ppm	1900	2048	1535	---
Barium	ppm	0	0	0	---
Boron	ppm	136	95	5	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: SCILAN
Unique No: 5681984
Signed: Wes Davis
Report Date: 16 Nov 2023



GRAPHS

