

## LIEBHERR PR736LGP 020009-1736 - Hydraulic System

Sample No: LH0277436

Oil Type: PETRO CANADA 10W30

#### **Sample Information**

Sample Number	LH0277436	LH0237754	LH0239692	
Sample Date	16 Nov 2023	02 Feb 2023	24 Aug 2022	
Machine Hours	2505	2011	1454	
Oil Hours	0	0	0	
Oil Changed	Not Changd	Changed	Not Changd	
Sample Status	ATTENTION	NORMAL	NORMAL	

Oil Co	ndition				F
Visc @ 40°C	cSt	52.9	● 45.5	0 45.7	
Acid Number (AN)	mg KOH/g		0 1.14		

Conta	mination				
Water	%	NEG	NEG	NEG	
Particles >4µm		<b>O</b> 30333	0 11406	11828	
Particles >6µm		0 5865	0 1494	0 1694	
Particles >14µm		0 287	99	78	
ISO 4406:1999 (c)		22/20/15	21/18/14	21/18/13	
Silicon	ppm	04	3	2	
Sodium	ppm	07	6	6	
Potassium	ppm	<b>○</b> <1	2	2	

#### **Wear Metals**

Iron	ppm	06	0 10	6	
Copper	ppm	04	0 6	<b>5</b>	
Lead	ppm	<b>○</b> <1	○ <1	01	
Tin	ppm	0 ()	0	0	
Aluminum	ppm	01	01	01	
Chromium	ppm	<mark>()</mark> <1	01	○ <1	
Molybdenum	ppm	0 31	6	04	
Nickel	ppm	0 🔘	○ <1	<1	
Titanium	ppm	4	5	5	
Silver	ppm	<1	0	0	
Manganese	ppm	0 🔘	○ <1	○ <1	
Vanadium	ppm	0	0	0	

0

24 C

Calcium	ppm	<b>0</b> 1201	0 1354	0 1291			
Magnesium	ppm	0 490	69	0 47			
Zinc	ppm	<b>970</b>	754	0 727			
Phosphorus	ppm	0 853	○ 709	637			
Barium	ppm	◯ <1	0	0			
Boron	ppm	○ 20	○ 31	32			





THOMAS CAVANAGH CONSTRUCTION LTD RR # 2, 9094 CAVANAGH ROAD ASHTON, ON CA K0A 1B0 Contact: Keith

T: (613)257-4995 F: (613)253-0071

### Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. Viscosity of sample indicates oil is within SAE 20 range, advise investigate. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: Report Date: CAVASH 5683555 Kevin Marson 24 Nov 2023 Submitted By: ?

# **LEBHERR** CONSTRUCTION EQUIPMENT



Graphs

