**CONSTRUCTION EQUIPMENT** 

## LIEBHERR LH50M 150728-1216 - Front Differential

Sample No: LH0242071

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

| ā                  |             |  |  |  |  |
|--------------------|-------------|--|--|--|--|
| SAMPLE INFORMATION |             |  |  |  |  |
| Sample Number      | LH0242071   |  |  |  |  |
| Sample Date        | 21 Nov 2023 |  |  |  |  |
| Machine Hours      | 500         |  |  |  |  |
| Oil Hours          | 500         |  |  |  |  |
| Oil Changed        | Changed     |  |  |  |  |
| Sample Status      | NORMAL      |  |  |  |  |
|                    |             |  |  |  |  |
| OIL CONDITION      |             |  |  |  |  |

| Campio Ctatao |                | HOHIMAL    |      |  |
|---------------|----------------|------------|------|--|
|               |                |            |      |  |
| OILCO         | <b>NDITION</b> |            |      |  |
| Visc @ 40°C   | cSt            | <b>138</b> | <br> |  |
|               |                |            |      |  |

| CONTAMINATION |     |          |  |  |  |  |  |
|---------------|-----|----------|--|--|--|--|--|
| Water         | %   | NEG      |  |  |  |  |  |
| Silicon       | ppm | <b>3</b> |  |  |  |  |  |
| Sodium        | ppm | <b>4</b> |  |  |  |  |  |
| Potassium     | ppm | <b>0</b> |  |  |  |  |  |

| O ME       |        |            |         |  |
|------------|--------|------------|---------|--|
| ₩ WEA      | R META | LS         |         |  |
| Iron       | ppm    | <b>6</b>   | <br>    |  |
| Copper     | ppm    | <b>23</b>  | <br>    |  |
| Lead       | ppm    | <b></b> <1 | <br>    |  |
| Tin        | ppm    | <b>0</b>   | <br>    |  |
| Aluminum   | ppm    | <b>0</b>   | <br>    |  |
| Chromium   | ppm    | <b>0</b>   | <br>    |  |
| Molybdenum | ppm    | <b>0</b>   | <br>    |  |
| Nickel     | ppm    | <1         | <br>    |  |
| Titanium   | ppm    | 0          | <br>    |  |
| Silver     | ppm    | <1         | <br>    |  |
| Manganese  | ppm    | <b>0</b>   | <br>    |  |
| Vanadium   | ppm    | 0          | <br>*** |  |

| vanadium   | ppm | U           |  |  |  |  |
|------------|-----|-------------|--|--|--|--|
| 6          |     |             |  |  |  |  |
| ADDITIVES  |     |             |  |  |  |  |
| Calcium    | ppm | <b>5</b>    |  |  |  |  |
| Magnesium  | ppm | <b>1</b>    |  |  |  |  |
| Zinc       | ppm | <b>18</b>   |  |  |  |  |
| Phosphorus | ppm | <b>1658</b> |  |  |  |  |
| Barium     | ppm | <b>4</b>    |  |  |  |  |
| Boron      | ppm | <b>136</b>  |  |  |  |  |



**ABC RECYCLING** 750C JACKSON RD NANAIMO, BC CA V9X 1J2

Contact: Jordie Richmond jordie.richmond@abcrecycling.com

T: (250)202-8235

F:

#### Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: **ABCNAN Unique No:** 5684401 Signed: Wes Davis Report Date: 28 Nov 2023

# LIEBHERR







### **GRAPHS**

