## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR LH50M 150728-1216 - Rear Differential

Sample No: LH0242072

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

5					
SAMPLEINFORMATION					
Sample Number	LH0242072				
Sample Date	21 Nov 2023				
Machine Hours	500				
Oil Hours	500				
Oil Changed	Changed				
Sample Status	NORMAL				
OIL CONDITION					

Visc @ 40°C	cSt	156				
and the						
CONTAMINATION						
Water	%	NEG				
Silicon	ppm	<b>12</b>				
Sodium	ppm	<b>2</b>				
Potassium	ppm	<b>()</b> <1				

<b>6</b>				
₩ WEA	R METALS			
Iron	ppm	<b>31</b>	 	
Copper	ppm	<b>24</b>	 	
Lead	ppm	<b>0</b> <1	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>0</b> <1	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>0</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	<b>()</b> <1	 	
Vanadium	ppm	0	 	

variaulum	ppiii	U					
ADDITIVES							
Calcium	ppm	<b>101</b>					
Magnesium	ppm	<b>0</b> <1					
Zinc	ppm	<b>18</b>					
Phosphorus	ppm	<b>1341</b>					
Barium	ppm	<b>2</b>					
Boron	ppm	○ 7					



ABC RECYCLING 750C JACKSON RD NANAIMO, BC CA V9X 1J2 Contact: Jordie Richmond

jordie.richmond@abcrecycling.com

T: (250)202-8235

F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: ABCNAN
Unique No: 5684403
Signed: Wes Davis
Report Date: 28 Nov 2023

# LIEBHERR

## CONSTRUCTION EQUIPMENT





### **GRAPHS**

