CONSTRUCTION EQUIPMENT



059596-194 - Front Differential

Sample No: LH0274776

Oil Type:

ø

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ADDITIVES

ppm

ppm

ppm

ppm

ppm

ppm

PETRO CANADA TRAXON 75W90 SYNTHETIC

SAMPLE INFORMATION				
Sample Number	LH0274776	LH0202696	LH0213824	LH0106357
Sample Date	23 Nov 2023	15 Nov 2022	04 Nov 2021	20 Sep 2016
Machine Hours	19244	17530	16550	8181
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL
OIL CONDITION				
Visc @ 40°C cSt	0 106	0 104	0 104	93.7

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	0 16	0 2	2	2
Sodium	ppm	01	◯ <1	○ <1	◯ <1
Potassium	ppm	0	○ <1	◯ <1	0 ()

WEA	R METALS				
Iron	ppm	○ <1	01	01	01
Copper	ppm	8	○ 31	26	28
Lead	ppm	○ <1	○ <1	◯ <1	○ <1
Tin	ppm	0	0	◯ <1	0
Aluminum	ppm	0	○ <1	0	○ <1
Chromium	ppm	0	0	0	0
Molybdenum	ppm	0	0	0	0
Nickel	ppm	0	0	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	<1	0	<1	0
Manganese	ppm	0	0	0	0
Vanadium	ppm	0	0	0	0

 $\bigcirc 7$

1

0 19

0

0 1332

0 320

 $\bigcirc 7$

 $\bigcirc 2$

0 16

0

0 330

0 1360

6

0

16

○ <1

1276

333

American Iron and Metal

2555 Sheffield Road Ottawa, ON CA K1B 3V6 Contact: Dan Dupelle ddupelle@aim-rg.com T: (613)228-9380 F: (613)745-0692

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	BAKOTT
Unique No:	5684826
Signed:	Wes Davis
Report Date:	30 Nov 2023

0 12

02

014

○ <1

0 300

0 1234





GRAPHS

0

