## ł BHERR **CONSTRUCTION EQUIPMENT**

## 059596-194 - Front Right Wheel Hub

PETRO CANADA TRAXON 75W90 SYNTHETIC

LH0274778 Sample No:

Oil Type:

Phosphorus

Barium

Boron

ppm

ppm

ppm

	PLE INFO	DRMATION			
Sample Number		LH0274778	LH0256516	LH0203092	LH0202914
Sample Date		23 Nov 2023	21 Mar 2023	15 Nov 2022	04 Nov 2021
Machine Hours		19244	18037	17530	16550
Oil Hours		0	0	0	0
Oil Changed		Changed	Changed	Changed	Changed
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
OIL C	ONDITIC	ON			
Visc @ 40°C	cSt	0 104	98.5	98.5	98.6
	TAMINA	TION			
Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	02	03	02	02
Sodium	ppm	<b>○</b> <1	◯ <1	◯ <1	◯ <1
Potassium	ppm	0 0 LS	○ <1	○ <1	○ <1
Iron	ppm	 9	0 19	0 16	0 13
Copper	ppm	01	0 1	0 1	○ <1
Lead	ppm	0	0	0	◯ <1
Tin	ppm	0 ()	○ <1	0	0 ()
Aluminum	ppm	<b>○</b> <1	◯ <1	◯ <1	0
Chromium	ppm	0 ()	0	0	0
Molybdenum	ppm	0 🔘	0	0	0
Nickel	ppm	<b>○</b> <1	0	0	0
Titanium	ppm	0 🔘	0	0	0
Silver	ppm	<1	0	0	<1
Manganese	ppm	0 🔘	◯ <1	◯ <1	◯ <1
Vanadium	ppm	0	0	0	0
ADD	ITIVES				
Calcium	ppm	7	06	5	04
Magnesium	ppm	01	01	01	01
Zinc	ppm	9	08	08	0 6
-	1= 1= · · · ·	<b>U</b> -	U -	0 -	U -

0 1346

○ <1

0 315

0 1307

0 <1

0 313

0 1366

◯ <1

◯ 332





an Iron and Metal

effield Road ON 3V6 Dan Dupelle aim-rg.com@ 228-9380 745-0692

## osis

ple at the next service interval tor.All component wear rates mal. There is no indication of tamination in the oil. The on of the oil is acceptable for e in service.

Depot:	BAKOTT		
Unique No:	5684833		
Signed:	Wes Davis		
Report Date:	30 Nov 2023		

0 1290

○ <1

0 283

Submitted By: Isabelle Langlois





GRAPHS

0

