

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH22 1197-098192 - Front Right Wheel Hub

Sample No: LH
Oil Type: NOT GIVEN



OMNI-RAIL INC.
1520 RUE JEAN-LACHINE
STE-CATHERINE, QC
CA J5C 1C2
Contact: Service Manager

T:
F:



SAMPLE INFORMATION

Sample Number	LH	---	---	---
Sample Date	30 Nov 2023	---	---	---
Machine Hours	1038	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	● 55.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	● 8	---	---	---
Sodium	ppm	● 24	---	---	---
Potassium	ppm	● 1	---	---	---



WEAR METALS

Iron	ppm	● 65	---	---	---
Copper	ppm	● 26	---	---	---
Lead	ppm	● <1	---	---	---
Tin	ppm	0	---	---	---
Aluminum	ppm	● 1	---	---	---
Chromium	ppm	● 2	---	---	---
Molybdenum	ppm	● 0	---	---	---
Nickel	ppm	● <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	● 3480	---	---	---
Magnesium	ppm	● 12	---	---	---
Zinc	ppm	● 1393	---	---	---
Phosphorus	ppm	● 1110	---	---	---
Barium	ppm	● 2	---	---	---
Boron	ppm	● 95	---	---	---

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Le fluide n'était pas spécifié, toutefois, une comparaison avec d'autres fluides indiqua que ce fluide est du SAE 80 Tractor TDH Fluid. Veuillez confirmer la viscosité de l'huile et veuillez préciser la marque de votre prochain échantillon. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: OMNSTE
Unique No: 5685731
Signed: Wes Davis
Report Date: 05 Dec 2023



GRAPHS

