LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L586 65883 - Front Axle

Sample No: LH0281165

Oil Type: LIEBHERR GEAR BASIC 90 LS



CONTAMINATION									
Water	%	NEG							
Silicon	ppm	7							
Sodium	ppm	2							
Potassium	ppm	○ <1							

WEA	R METAI	.S		
Iron	ppm	220	 	
Copper	ppm	132	 	
Lead	ppm	3	 	
Tin	ppm	8	 	
Aluminum	ppm	2	 	
Chromium	ppm	1	 	
Molybdenum	ppm	1	 	
Nickel	ppm	0 <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	8	 	
Vanadium	ppm	0	 	

variadium	ppm	U						
0								
ADDITIVES								
Calcium	ppm	18						
Magnesium	ppm	○ <1						
Zinc	ppm	121						
Phosphorus	ppm	2362						
Barium	ppm	0						
Boron	ppm	() <1						





Liebherr Canada

140 - 21320 Gordon Way Richmond, BC CA V6W 1J8 Contact: Kevin Steer kevin.steer@liebherr.com

T:

F: (604)270-3254

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LIERIC
Unique No: 5697814
Signed: Wes Davis
Report Date: 21 Dec 2023

Contact/Location: Kevin Steer - LIERIC

LIEBHERR







GRAPHS

