## LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### [AMICO] LIEBHERR Ta-230 150509 - Diesel Engine

Sample No: LH0281376

Oil Type: PETRO CANADA DURON UHP 5W30

SAMPLEINFORMATION						
Sample Number	LH0281376					
Sample Date	20 Dec 2023					
Machine Hours	35911					
Oil Hours	0					
Oil Changed	Changed					
Sample Status	NORMAL					
A						

OIL CO	NDITION			
Visc @ 100°C	cSt	<b>11.2</b>	 	
Oxidation (PA)	%	152	 	

CONTAMINATION					
Water	%	NEG			
Soot %	%	<b>0</b>			
Nitration (PA)	%	92			
Sulfation (PA)	%	89			
Glycol	%	<b>0.0</b>			
Fuel	%	<1.0			
Silicon	ppm	<b>10</b>			
Sodium	ppm	<b>6</b>			
Potassium	ppm	<b>5</b>			

WEA	R METALS			
Iron	ppm	<b>13</b>	 	
Copper	ppm	<b>274</b>	 	
Lead	ppm	<b>6</b>	 	
Tin	ppm	<b>1</b>	 	
Aluminum	ppm	<b>5</b>	 	
Chromium	ppm	<b>0</b> <1	 	
Molybdenum	ppm	<b>35</b>	 	
Nickel	ppm	<b>0</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	<b>0</b>	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	0	 	

ADI	DITIVES			
Calcium	ppm	1482	 	
Magnesium	ppm	753	 	
Zinc	ppm	910	 	
Phosphorus	ppm	801	 	
Barium	ppm	48	 	
Boron	ppm	<b>52</b>	 	



AMICO 44890 EDGEWARE LINE ST. THOMAS, ON CA N5P 3T3

Contact: Service Manager

T: F:

#### Diagnosis

being utilized for top-up/fill. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Confirm the source of the lubricant

Depot:AMISTTUnique No:5706935Signed:Kevin MarsonReport Date:04 Jan 2024

# LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

