# **CONSTRUCTION EQUIPMENT**

# LIEBHERR LH60M 146891-1217 - Hydraulic System

Sample No: LH0281175

**Oil Type:** 

# SAMPLE INFORMATION

Sample Number	LH0281175	 	
Sample Date	22 Dec 2023	 	
Machine Hours	519	 	
Oil Hours	0	 	
Oil Changed	Not Changd	 	
Sample Status	NORMAL	 	

PETRO CANADA HYDREX XV ALL SEASON HYDRAULIC OIL

**OIL CONDITION** 

Visc @ 40°C

#### cSt 0 44.8

Water	%	NEG			
Particles >4µm		0 909			
Particles >6µm		0 183			
Particles >14µm		9			
ISO 4406:1999 (c)		17/15/10			
Silicon	ppm	<b>3</b>			
Sodium	ppm	01			
Potassium	ppm	<mark>○</mark> <1			

# WEAR METALS

Iron	ppm	0 11	 	
Copper	ppm	<b>3</b>	 	
Lead	ppm	<b>○</b> <1	 	
Tin	ppm	0	 	
Aluminum	ppm	<b>○</b> <1	 	
Chromium	ppm	<b>○</b> <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>○</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

	DITIVES			
Calcium	ppm	1375	 	
Magnesium	ppm	04	 	
Zinc	ppm	696	 	
Phosphorus	ppm	620	 	
Barium	ppm	0 🔘	 	
Boron	ppm	0 ()	 	



### **RICHMOND STEEL RECYCLING**

11760 MITCHELL ROAD RICHMOND, BC CA V6V 1V8 Contact: Aaron Kaetler AKaetler@richmondsteel.ca T: F: (604)324-8617

## Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot: Unique No: Signed: **Report Date:**  RIC117RIC 5708246 Kevin Marson 11 Jan 2024

Submitted By: ?



# **LEBHERR** CONSTRUCTION EQUIPMENT



GRAPHS

Ö

