LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH50M 112359-1216 - Rear Differential

Sample No: LH0269702

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

_ _							
SAMPLE INFORMATION							
Sample Number	LH0269702	LH0224995	LH0221781	LH0151069			
Sample Date	03 Jan 2024	24 May 2023	02 Nov 2022	17 Feb 2022			
Machine Hours	7308	6000	5107	4009			
Oil Hours	0	0	0	0			
Oil Changed	Changed	N/A	Changed	Changed			
Sample Status	NORMAL	NORMAL	NORMAL	ABNORMAL			



CONTAMINATION						
Water	%	NEG	NEG	NEG	NEG	
Silicon	ppm	2	4	4	O 1	
Sodium	ppm	0 <1	1	4	3	
Potassium	ppm	0 <1	02	O <1	O <1	

(O)					
WEAR METALS					
Iron	ppm	10	O 15	○ 34	O 19
Copper	ppm	20	0 8	16	O 10
Lead	ppm	() <1	O	<1	0
Tin	ppm	0	O 0	0	O <1
Aluminum	ppm	() <1	O <1	O <1	0
Chromium	ppm	0	O 0	0	0
Molybdenum	ppm	0	O	0	0
Nickel	ppm	○ <1	O <1	O <1	O <1
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	0	O <1	1	O <1
Vanadium	ppm	0	0	0	0

Vanadium	ppm	0	0	0	0	
ADDITIVES						
Calcium	ppm	13	O 22	O 4	O 5	
Magnesium	ppm	1	O 2	O <1	O <1	
Zinc	ppm	20	O 25	O 12	10	
Phosphorus	ppm	1208	O 1328	1607	2261	
Barium	ppm	0	O 0	O	O <1	
Boron	ppm	290	O 261	186	28	



RICHMOND STEEL 12707 170 STREET EDMONTON, AB CA T5V 1L9

Contact: Sandor Arguello

T: (780)447-3391

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RICEDMUnique No:5708279Signed:Kevin MarsonReport Date:08 Jan 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

