CONSTRUCTION EQUIPMENT

LIEBHERR LH40M 146308-1215 - Rear Differential

Sample No: LH0281097

PETRO CANADA TRAXON SYNTHETIC 75W90 Oil Type:

a					
SAMPLEINFORMATION					
Sample Number	LH0281097				
Sample Date	03 Jan 2024				
Machine Hours	511				
Oil Hours	0				
Oil Changed	Changed				
Sample Status	NORMAL				

Oil Changed		Changed					
Sample Status		NORMAL					
OIL CONDITION							
Visc @ 40°C	cSt	131					

CONTAMINATION							
Water	%	NEG					
Silicon	ppm	7					
Sodium	ppm	27					
Potassium	ppm	3					

Ø WEA				
WEA	R META	LS		
Iron	ppm	76	 	
Copper	ppm	61	 	
Lead	ppm	3	 	
Tin	ppm	0	 	
Aluminum	ppm	2	 	
Chromium	ppm	() <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	○ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	

variadium	ppm	U				
0						
ADDITIVES						
Calcium	ppm	17				
Magnesium	ppm	2				
Zinc	ppm	40				
Phosphorus	ppm	1560				
Barium	ppm	() <1				
Boron	ppm	184				



RICHMOND STEEL RECYCLING

955 ORD ROAD KAMLOOPS, BC CA V2B 7B5

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: RIC955KAM **Unique No:** 5708351 Signed: Wes Davis **Report Date:** 09 Jan 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

