

# LIEBHERR

## CONSTRUCTION EQUIPMENT



### LIEBHERR LH22M 136874-1250 - Rear Right Wheel Hub

Sample No: LH

Oil Type: LIEBHERR GEAR BASIC 90 LS



LA REGIE DES MATIERES RESIDUELLES DU LAC ST-JEAN  
625 RUE BERGERON OUEST  
ALMA, QC  
CA G8B 1V3  
Contact: Service Manager



#### SAMPLE INFORMATION

Sample Number	LH	LH0249968	---	---
Sample Date	05 Jan 2024	25 Jan 2023	---	---
Machine Hours	1000	500	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---



#### OIL CONDITION

Visc @ 40°C	cSt	166	64.7	---	---
-------------	-----	-----	------	-----	-----

T:  
F:



#### CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	4	7	---	---
Sodium	ppm	4	14	---	---
Potassium	ppm	<1	<1	---	---

#### Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.



#### WEAR METALS

Iron	ppm	20	14	---	---
Copper	ppm	2	7	---	---
Lead	ppm	0	0	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	<1	<1	---	---
Chromium	ppm	<1	<1	---	---
Molybdenum	ppm	0	0	---	---
Nickel	ppm	<1	<1	---	---
Titanium	ppm	0	<1	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	1	2	---	---
Vanadium	ppm	0	0	---	---



#### ADDITIVES

Calcium	ppm	616	3581	---	---
Magnesium	ppm	3	10	---	---
Zinc	ppm	255	1423	---	---
Phosphorus	ppm	2084	1217	---	---
Barium	ppm	0	0	---	---
Boron	ppm	15	103	---	---

Depot: LARALM  
Unique No: 5709705  
Signed: Wes Davis  
Report Date: 12 Jan 2024



### GRAPHS

