

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH80M 120282-1218 - Rear Differential

Sample No: LH0279397

Oil Type: CHEVRON DELO SYNTHETIC GEAR 75W90



ARCELORMITTAL LONG PRODUITS CANADA
3185 ROUTE MARIE-VICTORIN
CONTRECOEUR, QC
CA J0L 1C0
Contact: Danny Drouin
danny.drouin@arcelormittal.com
T:
F:



SAMPLE INFORMATION

Sample Number	LH0279397	LH0280269	LH0270037	LH0261215
Sample Date	12 Jan 2024	02 Dec 2023	27 Sep 2023	01 Jul 2023
Machine Hours	12934	12550	11869	11397
Oil Hours	0	0	0	0
Oil Changed	Changed	Changed	Changed	Changed
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL



OIL CONDITION

Visc @ 40°C	cSt	105	104	104	104



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	2	3	4	4
Sodium	ppm	1	4	4	3
Potassium	ppm	<1	<1	0	<1



WEAR METALS

Iron	ppm	10	24	23	18
Copper	ppm	<1	3	3	1
Lead	ppm	0	<1	<1	0
Tin	ppm	0	0	0	0
Aluminum	ppm	<1	<1	<1	<1
Chromium	ppm	0	0	0	0
Molybdenum	ppm	0	0	0	<1
Nickel	ppm	<1	<1	<1	<1
Titanium	ppm	0	0	0	0
Silver	ppm	0	<1	<1	0
Manganese	ppm	0	<1	<1	<1
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	25	7	8	7
Magnesium	ppm	<1	<1	1	2
Zinc	ppm	15	12	14	12
Phosphorus	ppm	1371	1383	1393	1469
Barium	ppm	0	<1	<1	0
Boron	ppm	256	252	240	258

Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition. Les taux d'usure de tous les composants sont normaux. Il n'y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot: MITCON
Unique No: 5710182
Signed: Kevin Marson
Report Date: 16 Jan 2024



GRAPHS

