LIEBHERR

CONSTRUCTION EQUIPMENT



[(337755)] LIEBHERR L556 057483-1332 - Diesel Engine

Sample No: LH

~

Oil Type: {unknown}

- T			
SAMPLEIN	FORMATION		
Sample Number	LH	 	
Sample Date	22 Jan 2024	 	
Machine Hours	7383	 	
Oil Hours	0	 	
Oil Changed	N/A	 	
Sample Status	MARGINAL	 	
A			

OILC	ONDITION	ı		
Visc @ 100°C	cSt	12.2	 	
Oxidation (PA)	%	111	 	
**				

CON'	TAMIN	ATION		
Water	%	NEG	 	
Soot %	%	0	 	
Nitration (PA)	%	118	 	
Sulfation (PA)	%	71	 	
Glycol	%	NEG	 	
Fuel	%	2.3	 	
Silicon	ppm	8	 	
Sodium	ppm	5	 	
Potassium	ppm	4	 	

₩EA	AR META	LS		
Iron	ppm	9	 	
Copper	ppm	4	 	
Lead	ppm	O <1	 	
Tin	ppm	O <1	 	
Aluminum	ppm	4	 	
Chromium	ppm	○ <1	 	
Molybdenum	ppm	58	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

Variadium	ppiii	· ·		
ADI	DITIVES			
Calcium	ppm	856	 	
Magnesium	ppm	1118	 	
Zinc	ppm	1208	 	
Phosphorus	ppm	1008	 	
Barium	ppm	0	 	
Boron	ppm	13	 	



LES CHARGEMENTS ERIC TURPIN 1170 CHEMIN DES VILLAS MONT-LAURIER, QC CA J9L 3G7

Contact: ERIC TURPIN

T: (819)660-9886 F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 30 Diesel Engine Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample. All component wear rates are normal. Light fuel dilution occurring. No other contaminants were detected in the oil. The condition of the oil is acceptable for the time in service.

Depot:LES11DESUnique No:5711597Signed:Kevin MarsonReport Date:24 Jan 2024





GRAPHS

