LIEBHERR

CONSTRUCTION EQUIPMENT



[(375856)] LIEBHERR R930 049712-1716 - Swing Drive

Sample No: LH0231976

Oil Type: GEAR OIL SAE 75W90

<u> </u>						
SAMPLEINFORMATION						
Sample Number		LH0231976	LH0231969			
Sample Date		05 Jan 2024	22 Sep 2022			
Machine Hours		2014	1000			
Oil Hours		0	0			
Oil Changed		Changed	Not Changd			
Sample Status		NORMAL	NORMAL			
OIL CONDITION						
Visc @ 40°C	cSt	116	135			

CON	TAMIN/	ATION		
Water	%	NEG	NEG	
Silicon	ppm	3	O <1	
Sodium	ppm	2	O <1	
Potassium	ppm	1	O 1	

Iron ppm ○ 144 ○ <1		}	R METALS	WEAL
Lead ppm 0 0 Tin ppm 0 0 Aluminum ppm <1 0 Chromium ppm 2 0 Molybdenum ppm 0 <1 Nickel ppm <1 0	 O <1	144	ppm	Iron
Tin ppm 0 0 Aluminum ppm 0 Chromium ppm 0 0 Molybdenum ppm 0 <1	 0	0 <1	ppm	Copper
Aluminum ppm 0 Chromium ppm 2 0 Molybdenum ppm 0 <1	 0	0	ppm	Lead
Chromium ppm 2 0 Molybdenum ppm 0 <1	 0	0	ppm	Tin
Molybdenum ppm ○ 0 <1 Nickel ppm ○ <1 0	 0	0 <1	ppm	Aluminum
Nickel ppm	 0	2	ppm	Chromium
	 O <1	0	ppm	Molybdenum
Titanium ppm 0 0	 0	○ <1	ppm	Nickel
	 0	0	ppm	Titanium
Silver ppm 0 0	 0	0	ppm	Silver
Manganese ppm ○ <1 ○ 0	 0	() <1	ppm	Manganese
Vanadium ppm 0	 0	0	ppm	Vanadium

variaululli	ppiii	U	U			
ADDI						
ADDITIVES						
Calcium	ppm	5	18			
Magnesium	ppm	0 <1	O 0			
Zinc	ppm	9	O 26			
Phosphorus	ppm	1388	906			
Barium	ppm	3	O 0			
Boron	ppm	151	O 124			



COUNTY OF ST. PAUL NO. 19 5015 - 49 AVENUE

ST. PAUL, AB CA T0A 3A4 Contact: Brent Lilje blilje@county.stpaul.ab.ca

T: (780)645-3006

F:

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: COU501STP
Unique No: 5721305
Signed: Wes Davis
Report Date: 30 Jan 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

