# LIEBHERR

## **CONSTRUCTION EQUIPMENT**



### LIEBHERR L566 054116-1484 - Transmission (Manual)

**Sample No:** LH0281172

Oil Type: PETRO CANADA DURATRAN

5					
SAMPLEINFORMATION					
Sample Number		LH0281172	LH0281152	LH0135632	
Sample Date		26 Jan 2024	04 Jan 2024	14 Dec 2021	
Machine Hours		9754	9598	5482	
Oil Hours		0	0	0	
Oil Changed		Not Changd	Changed	Changed	
Sample Status		ABNORMAL	ABNORMAL	NORMAL	
OIL CONDITION					
Visc @ 40°C	cSt	<b>41.3</b>	35.4	○ 36.6	

CONTAMINATION						
Water	%	NEG	NEG	NEG		
Silicon	ppm	<b>10</b>	<b>8</b>	0 8		
Sodium	ppm	<b>1</b>	<b>3</b>	<b>9</b>		
Potassium	ppm	<b>○</b> <1	O 1	○ 3		

WEA	R METAL	S			
Iron	ppm	<b>37</b>	O 34	O 50	
Copper	ppm	<b>○</b> <1	O 1	<b>3</b>	
Lead	ppm	<b>0</b>	O <1	O <1	
Tin	ppm	<b>0</b>	O 0	<b>0</b>	
Aluminum	ppm	<b>2</b>	O 2	<b>1</b>	
Chromium	ppm	<b>0</b>	O 0	O <1	
Molybdenum	ppm	<b>0</b>	O 0	O <1	
Nickel	ppm	<b></b> <1	O <1	O <1	
Titanium	ppm	0	0	0	
Silver	ppm	<b>0</b>	O 0	O <1	
Manganese	ppm	<b>0</b>	<b>0</b>	<1	
Vanadium	ppm	0	0	0	

ADDITIVES						
Calcium	ppm	<b>3830</b>	3267	3248		
Magnesium	ppm	<b>17</b>	<b>1</b> 0	O 11		
Zinc	ppm	<b>1474</b>	<b>1339</b>	<b>1366</b>		
Phosphorus	ppm	<b>1205</b>	O 1108	<b>1187</b>		
Barium	ppm	<b>0</b>	<b>0</b>	O		
Boron	ppm	<b>107</b>	○ 89	96		



Abbycel Substrate Ltd. 3545 Ross Road Abbotsford, BC CA V4X 1M6

Contact: Service Manager

T: F:

#### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid.

Viscosity of sample indicates oil is within SAE 75W80 range, advise investigate. The condition of the fluid is acceptable for the time in service.

Depot: ABB354ABB
Unique No: 5721971
Signed: Bill Quesnel
Report Date: 01 Feb 2024

## LIEBHERR

CONSTRUCTION EQUIPMENT





### **GRAPHS**

