

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH60M 147037-1217 - Rear Right Wheel Hub

Sample No: LH0131740

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



STELLA JONES INC
 25 BRAID ST
 NEW WESTMINSTER, BC
 CA V3L 3P2
 Contact: Richard Vogel
 rvogel@stella-jones.com
 T: (604)999-9220
 F: (604)526-8597



SAMPLE INFORMATION

Sample Number	LH0131740	LH0271335	---	---
Sample Date	03 Feb 2024	31 Oct 2023	---	---
Machine Hours	2067	1062	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---



OIL CONDITION

Visc @ 40°C	cSt	98.7	103	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	3	3	---	---
Sodium	ppm	3	2	---	---
Potassium	ppm	1	0	---	---



WEAR METALS

Iron	ppm	22	14	---	---
Copper	ppm	6	7	---	---
Lead	ppm	0	<1	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	<1	<1	---	---
Chromium	ppm	0	0	---	---
Molybdenum	ppm	0	0	---	---
Nickel	ppm	0	0	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	<1	---	---
Manganese	ppm	0	0	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	18	11	---	---
Magnesium	ppm	<1	<1	---	---
Zinc	ppm	13	10	---	---
Phosphorus	ppm	1252	1266	---	---
Barium	ppm	0	<1	---	---
Boron	ppm	308	315	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: STE25NEW
 Unique No: 5722891
 Signed: Wes Davis
 Report Date: 06 Feb 2024



GRAPHS

