

LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR LH60M 147037-1217 - Front Left Wheel Hub

Sample No: LH0131739

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



STELLA JONES INC
 25 BRAID ST
 NEW WESTMINSTER, BC
 CA V3L 3P2
 Contact: Richard Vogel
 rvogel@stella-jones.com
 T: (604)999-9220
 F: (604)526-8597



SAMPLE INFORMATION

Sample Number	LH0131739	LH0271332	---	---
Sample Date	03 Feb 2024	31 Oct 2023	---	---
Machine Hours	2067	1062	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	NORMAL	---	---



OIL CONDITION

Visc @ 40°C	cSt	90.5	102	---	---
-------------	-----	------	-----	-----	-----



CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	1	2	---	---
Sodium	ppm	1	2	---	---
Potassium	ppm	1	0	---	---



WEAR METALS

Iron	ppm	107	78	---	---
Copper	ppm	14	14	---	---
Lead	ppm	<1	<1	---	---
Tin	ppm	0	0	---	---
Aluminum	ppm	1	<1	---	---
Chromium	ppm	<1	<1	---	---
Molybdenum	ppm	0	0	---	---
Nickel	ppm	0	<1	---	---
Titanium	ppm	0	0	---	---
Silver	ppm	0	<1	---	---
Manganese	ppm	1	1	---	---
Vanadium	ppm	0	0	---	---



ADDITIVES

Calcium	ppm	11	12	---	---
Magnesium	ppm	<1	<1	---	---
Zinc	ppm	16	18	---	---
Phosphorus	ppm	1265	1334	---	---
Barium	ppm	1	4	---	---
Boron	ppm	299	297	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: STE25NEW
 Unique No: 5722909
 Signed: Wes Davis
 Report Date: 06 Feb 2024



GRAPHS

