LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR T60-9 024742-1709 - Diesel Engine

Sample No: LH0279129

Oil Type: PETRO CANADA DURON UHP 10W40

5						
SAMPLEINFORMATION						
Sample Number	LH0279129	LH				
Sample Date	01 Feb 2024	18 Apr 2023				
Machine Hours	1012	500				
Oil Hours	0	0				
Oil Changed	Changed	N/A				
Sample Status	NORMAL	NORMAL				
A						

OIL CONDITION							
Visc @ 100°C	cSt	13.7	O 12.3				
Oxidation (PA)	%	55	42				

CONTAMINATION						
Water	%	NEG	NEG			
Soot %	%	0.1	0.1			
Nitration (PA)	%	59	89			
Sulfation (PA)	%	50	46			
Glycol	%	NEG	NEG			
Fuel	%	<1.0	<1.0			
Silicon	ppm	7	O 22			
Sodium	ppm	2	4			
Potassium	ppm	() <1	O 1			

(0)				
WE!	AR METAI	.S		
Iron	ppm	24	O 48	
Copper	ppm	3	O 10	
Lead	ppm	○ <1	O <1	
Tin	ppm	2	3	
Aluminum	ppm	10	O 11	
Chromium	ppm	1	O 2	
Molybdenum	ppm	53	4	
Nickel	ppm	○ <1	O <1	
Titanium	ppm	0	O <1	
Silver	ppm	0	0	
Manganese	ppm	<1	4	
Vanadium	ppm	0	0	

ADDITIVES						
Calcium	ppm	1271	○ 3903			
Magnesium	ppm	881	240			
Zinc	ppm	1144	O 1215			
Phosphorus	ppm	996	O 1169			
Barium	ppm	0	O 2			
Boron	ppm	13	O 204			



LES EQUIPEMENTS SPM 551 RUE J OSWALD FOREST SAINT-ROCH-DE-L'ACHIGAN, QC CA J0K 3H0

Contact: Service Manager

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 LES551SAI2

 Unique No:
 5723080

 Signed:
 Wes Davis

 Report Date:
 07 Feb 2024

LIEBHERR







GRAPHS

