LIEBHERR

CONSTRUCTION EQUIPMENT



LIEBHERR L580 067666-1760 - Transmission (Manual)

Sample No: LH0233939
Oil Type: SAE 10W30

5						
SAMPLEIN	NFORMATION					
Sample Number	LH0233939	LH0176021	LH0234005			
Sample Date	22 Jan 2024	02 Aug 2023	15 Dec 2022			
Machine Hours	5478	1520	1018			
Oil Hours	0	0	0			
Oil Changed	Changed	Changed	Changed			
Sample Status	ABNORMAL	NORMAL	NORMAL			
OIL CONDITION						
Visc @ 40°C cSt	47.0	○ 38.7	44.4			
CONTAMINATION						

CONTAMINATION								
Water	%	NEG	NEG	NEG				
Silicon	ppm	5	0 8	4				
Sodium	ppm	5	6	O 1				
Potassium	ppm	() <1	O <1	1				

Ø WE					
WE/	AR META	LS			
Iron	ppm	35	O 10	4	
Copper	ppm	28	O 1	O 2	
Lead	ppm	1	O	5	
Tin	ppm	○ <1	O 0	O 0	
Aluminum	ppm	2	O <1	O 1	
Chromium	ppm	() <1	O 0	O 0	
Molybdenum	ppm	36	O <1	0	
Nickel	ppm	○ <1	O 0	<1	
Titanium	ppm	0	0	0	
Silver	ppm	0	O 0	0	
Manganese	ppm	5	O <1	<1	
Vanadium	ppm	0	0	0	

0					
	TIVES				
Calcium	ppm	1999	○ 3704	1320	
Magnesium	ppm	550	O 12	10	
Zinc	ppm	1121	O 1508	677	
Phosphorus	ppm	1013	O 1299	652	
Barium	ppm	() <1	O 0	0	
Boron	ppm	6	108	2	



WEST CARLETON SAND & GRAVEL INC.

3232 CARP ROAD CARP, ON CA K0A 1L0 Contact: Troy Whalen twhalen@acon.com T: (613)836-3090 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. Viscosity of sample indicates oil is within SAE 10W range, advise investigate. The condition of the fluid is acceptable for the time in service.

 Depot:
 WES654STI

 Unique No:
 5723189

 Signed:
 Kevin Marson

 Report Date:
 08 Feb 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

