LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR L580 067666-1760 - Front Differential

Sample No: LH0233934

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

5					
SAMP	LE INFOR <i>i</i>	MOITAN			
Sample Number		LH0233934	LH0176019	LH0234000	
Sample Date		22 Jan 2024	02 Aug 2023	15 Dec 2022	
Machine Hours		5478	1520	1018	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		NORMAL	NORMAL	NORMAL	
OIL CONDITION					
Visc @ 40°C	cSt	95.8	100	O 194	
CONTAMINATION					

CONTAMINATION						
Water	%	NEG	NEG	NEG		
Silicon	ppm	○ <1	6	27		
Sodium	ppm	○ <1	3	0 8		
Potassium	ppm	O <1	O <1	2		

WEA	R METALS	3			
Iron	ppm	9	6 7	240	
Copper	ppm	 <1	O 75	O 177	
Lead	ppm	 <1	O 2	4	
Tin	ppm	0	3	O 12	
Aluminum	ppm	 <1	O <1	O 2	
Chromium	ppm	0	O <1	O 2	
Molybdenum	ppm	0	O 0	O <1	
Nickel	ppm	0	O <1	O 1	
Titanium	ppm	0	O 0	O <1	
Silver	ppm	0	0	0	
Manganese	ppm	0	O 14	53	
Vanadium	ppm	0	0	<1	

ADDITIVES						
Calcium	ppm	7 0	5	O 12		
Magnesium	ppm	O <1	O 1	O 2		
Zinc	ppm	29	38	156		
Phosphorus	ppm	1223	2551	2282		
Barium	ppm	0	O	O 0		
Boron	ppm	182	○ 203	O 2		



WEST CARLETON SAND & GRAVEL INC.

3232 CARP ROAD CARP, ON CA K0A 1L0 Contact: Troy Whalen twhalen@acon.com

twhalen@acon.com T: (613)836-3090

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 WES654STI

 Unique No:
 5723201

 Signed:
 Wes Davis

 Report Date:
 07 Feb 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

