

# LIEBHERR L580 73441 - Splitter Box

Sample No: LH0275828

Oil Type: LIEBHERR GEAR BASIC 90 LS

## SAMPLE INFORMATION

Sample Number	LH0275828	 	
Sample Date	06 Dec 2023	 	
Machine Hours	1043	 	
Oil Hours	0	 	
Oil Changed	N/A	 	
Sample Status	NORMAL	 	

**OIL** 

#### **OIL CONDITION**

Visc @ 40°C

.

### cSt 🔘 193

Water	%	NEG			
Silicon	ppm	0 2			
Sodium	ppm	<b>○</b> <1			
Potassium	ppm	01			

Ä				
WEA	<b>R METALS</b>			
Iron	ppm	26	 	
Copper	ppm	<b>2</b>	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	<b>○</b> <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	01	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	<b>○</b> <1	 	
Vanadium	ppm	0	 	

ADDITIVES

Calcium	ppm	<b>0</b> 10	 	
Magnesium	ppm	04	 	
Zinc	ppm	0 26	 	
Phosphorus	ppm	<b>2300</b>	 	
Barium	ppm	<b>○</b> <1	 	
Boron	ppm	<b>O</b> <1	 	





ArcelorMittal Mines Canada

1000 Route 389, (Mont-Wright) Fermont, QC CA G0G 1J0 Contact: Alexandre Lévesque alexandre.levesque@arcelormittal.com T: (418)287-4700 F:

#### Diagnosis

Échantillonner de nouveau l'équipement au prochain intervalle de vidange afin d'en surveiller la condition.Les taux d'usure de tous les composants sont normaux. Il n`y a aucun indice de contamination dans l'huile. L'état de l'huile est acceptable pour la durée de service.

Depot:AFUnique No:57Signed:WoReport Date:15

ARCFER 5733173 Wes Davis 15 Feb 2024

# CONSTRUCTION EQUIPMENT



GRAPHS

 $\odot$ 

