LIEBHERR





[ZANCON FOUNDATIONS] LIEBHERR LB28 115549 - Splitter Bo

Sample No: LH0216132

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

_				
SAMI	PLE INFOR/	MATION		
Sample Number		LH0216132	 	
Sample Date		14 Feb 2024	 	
Machine Hours		6134	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OILCO	ONDITION			
Visc @ 40°C	cSt	180	 	

CONTAMINATION						
Water	%	NEG				
Silicon	ppm	2				
Sodium	ppm	1				
Potassium	ppm	0 <1				
JAN.						

(O) WE	D 44FE 4			
WEA	IR META	LS		
Iron	ppm	15	 	
Copper	ppm	() <1	 	
Lead	ppm	0	 	
Tin	ppm	0 0	 	
Aluminum	ppm	1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

ADDITIVES					
Calcium	ppm	20			
Magnesium	ppm	0 1			
Zinc	ppm	41			
Phosphorus	ppm	1066			
Barium	ppm	0			
Boron	ppm	0 <1			



LIEBHERR CANADA LTD.

1015 SUTTON DRIVE
BURLINGTON, ON
CA L7L 5Z8
Contact: Steve Lehto
steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5733533Signed:Wes DavisReport Date:20 Feb 2024

Contact/Location: Steve Lehto - LIEMIS

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

