# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### LIEBHERR LH40M 156305-1215 - Front Right Wheel Hub

Sample No: LH0278471

Oil Type: GEAR OIL SAE 80W90

5						
SAMPLE INFORMATION						
Sample Number	LH0278471					
Sample Date	20 Feb 2024					
Machine Hours	536					
Oil Hours	0					
Oil Changed	Changed					
Sample Status	NORMAL					
<b>A</b>						

	OIL CC	NDITION			
/isc @	40°C	cSt	<b>140</b>	 	

CONTAMINATION									
Water	%	NEG							
Silicon	ppm	<b>9</b>							
Sodium	ppm	<b>5</b>							
Potassium	ppm	<b>2</b>							

(O) WE	D 44FE 4	1.0		
WEA	IR META	LS		
Iron	ppm	<b>44</b>	 	
Copper	ppm	<b>37</b>	 	
Lead	ppm	<b>1</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>O</b> <1	 	
Molybdenum	ppm	<b>()</b> <1	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	<b>0</b>	 	
Silver	ppm	0	 	
Manganese	ppm	<b>3</b>	 	
Vanadium	ppm	0	 	

0				
ADDI	TIVES			
Calcium	ppm	<b>135</b>	 	
Magnesium	ppm	<b>2</b>	 	
Zinc	ppm	<b>45</b>	 	
Phosphorus	ppm	<b>1449</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>4</b>	 	



Urban Mine
72 Rothwell Rd.
Winnipeg, MB
CA R3P 2H7
Contact: SERVICE

T: (204)774-0192

F:

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:URBWINUnique No:5734616Signed:Wes DavisReport Date:22 Feb 2024

## LIEBHERR







#### **GRAPHS**

