## CONSTRUCTION EQUIPMENT



PETRO CANADA TRAXON 75W90 SYNTHETIC

Sample No: LH0281250

Oil Type:

## **SAMPLE INFORMATION**

Sample Number	LH0281250	LH0202599	 
Sample Date	07 Feb 2024	20 Oct 2021	 
Machine Hours	5387	584	 
Oil Hours	0	0	 
Oil Changed	Changed	Changed	 
Sample Status	NORMAL	NORMAL	 
OIL CONDITION			
Visc @ 40°C cSt	0 149	147	 

Water	%	NEG	NEG		
Silicon	ppm	07	0 13		
Sodium	ppm	04	6		
Potassium	ppm	<b>○</b> <1	$\bigcirc 2$		

Ä				
₩ WE/	AR META	LS		
			0.40	
Iron	ppm	<b>58</b>	0 42	 
Copper	ppm	03	0 14	 
Lead	ppm	0 🔘	○ <1	 
Tin	ppm	0	○ <1	 
Aluminum	ppm	01	2	 
Chromium	ppm	<mark></mark> <1	○ <1	 
Molybdenum	ppm	0	2	 
Nickel	ppm	<b>○</b> <1	○ <1	 
Titanium	ppm	0	0	 
Silver	ppm	0	<1	 
Manganese	ppm	<b>()</b> <1	0 2	 
Vanadium	ppm	0	0	 

<b>ADD</b>	ITIVES			
Calcium	ppm	● 20	0 180	 
Magnesium	ppm	0 2	02	 
Zinc	ppm	<b>10</b>	54	 
Phosphorus	ppm	1990	2057	 
Barium	ppm	0	◯ <1	 
Boron	ppm	71	8 🔾	 





American Iron and Metal

75 Steel City Court Hamilton, ON CA L8H 3Y2 Contact: Heavy Equipment hamiltonmobileassetmaintenance@aim-recycling.com T: (905)547-5533 F: (905)544-5671

## Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:ANUnique No:57Signed:WReport Date:01

AMEHAM 5736464 Wes Davis 01 Mar 2024





GRAPHS

 $\odot$ 

