LIEBHERR

CONSTRUCTION EQUIPMENT

[(351064)] 122398-1216 - Splitter Box

Sample No: LH0281248

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC



CONTAMINATION							
Water % NEG NEG NEG	NEG						
Silicon ppm Q 2 Q 4	1						
Sodium	4						
Potassium ppm O<1	2						

WEAR METALS								
Iron	ppm	11	O 16	O <1	20			
Copper	ppm	0 <1	O <1	O 0	3			
Lead	ppm	0	O 0	O 0	O 0			
Tin	ppm	0	0	O 0	0			
Aluminum	ppm	○ <1	O 1	O 0	O <1			
Chromium	ppm	0	0	O 0	O <1			
Molybdenum	ppm	0	0	O 0	O <1			
Nickel	ppm	O <1	O <1	0	O <1			
Titanium	ppm	0	0	0	0			
Silver	ppm	0	0	0	0			
Manganese	ppm	0	0	0	3			
Vanadium	ppm	0	0	0	0			

Vanadium	ppm	0	0	Ü	0			
ADDITIVES								
Calcium	ppm	42	○ 66	O <1	O 21			
Magnesium	ppm	4	O 11	0	O 11			
Zinc	ppm	53	O 77	O 2	6 7			
Phosphorus	ppm	1569	2022	2390	1579			
Barium	ppm	0	O 0	0	O 2			
Boron	ppm	171	57	4	O 2			



American Iron and Metal

75 Steel City Court Hamilton, ON CA L8H 3Y2

Contact: Heavy Equipment

hamiltonmobileassetmaintenance@aim-recycling.com

T: (905)547-5533 F: (905)544-5671

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: AMEHAM
Unique No: 5736466
Signed: Wes Davis
Report Date: 01 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

