LIEBHERR





Sample No: LH0270176

Oil Type: TDH FLUID SAE 75W80

_					
SAMPLE INFORMATION					
Sample Number		LH0270176			
Sample Date		03 Mar 2024			
Machine Hours		2090			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
A Clarac		110111111111			
OII C	ONDITIO	N			
Visc @ 40°C	cSt	42.1			
CONT	[AMINA]	TION			
Water	%	NEG			
Silicon	ppm	8			
Sodium	ppm	16			
Potassium	ppm	2			
◎ WEΔ	R METAL	S			
Iron	ppm	14			
Copper	ppm	3			
Lead	ppm	O <1			
Tin	ppm	0 0			
Aluminum	ppm	O 2			
Chromium	ppm	0			
Molybdenum	ppm	0			
Nickel	ppm	O <1			
Titanium	ppm	0		***	***
Silver	ppm	0			
Manganese	ppm	0			
Vanadium	ppm	0			
ADDI	TIVES				
Calcium	ppm	3427			
Magnesium	ppm	9			
Zinc	ppm	1407			
Phosphorus	ppm	0 1172			
Barium	ppm	0 0			

LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8

Contact: Joseph Rodgers joseph.rodgers@liebherr.com

T:

F: (905)319-6622

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDH FLUID SAE 75W80. Please confirm.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: LIEMIS
Unique No: 5736713
Signed: Kevin Marson
Report Date: 04 Mar 2024

Boron

LIEBHERR







GRAPHS

