# EBHERR



### LIEBHERR L550 73936 - Transmission (Manual)

Sample No: LH0278692

Oil Type: **TDH FLUID SAE 75W80** 

_					
SAMPLE INFORMATION					
Sample Number		LH0278692			
Sample Date		03 Mar 2024			
Machine Hours		2179			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
A TOTAL LE					
	ONDITION				
	ONDITION	<b>u</b>			
Visc @ 40°C	cSt	<b>42.2</b>			
CONT	<b>TAMINAT</b>	ION			
Water	%	NEG			
Silicon					
	ppm	<b>9</b>			
Sodium Potassium	ppm	<b>15</b>			
	ppm	<b>3</b>			
(O) WEA					
WEA	R METALS				
Iron	ppm	<b>18</b>			
Copper	ppm	<b>3</b>			
Lead	ppm	<b>0</b> <1			
Tin	ppm	<b>0</b>			
Aluminum	ppm	<b>2</b>			
Chromium	ppm	<b>0</b>			
Molybdenum	ppm	<b>0</b>			
Nickel	ppm	<b>0</b>			
Titanium	ppm	0			
Silver	ppm	<b>0</b>			
Manganese	ppm	<b>0</b>			
Vanadium	ppm	0			
ADDI	TIVES				
Calcium	ppm	<b>3449</b>			
Magnesium	ppm	07			
Zinc	ppm	<b>1408</b>			
Phosphorus	ppm	<b>1173</b>			
Barium	ppm	<b>0</b> 0			
_		<u> </u>			

#### LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON

CA L7L 5Z8

Contact: Steve Lehto steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDH FLUID SAE 75W80. Please confirm.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: LIEMIS Unique No: 5736714 Signed: Kevin Marson **Report Date:** 04 Mar 2024

Contact/Location: Steve Lehto - LIEMIS

Boron

## LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

