LIEBHERR





[PRO CAISSONS [601832]] LIEBHERR LB35 115695 - Splitter Bo

Sample No: LH0286715

Oil Type: PETRO CANADA TRAXON SYNTHETIC 75W90

Ō SAMDIEI	INFORMATION		
Sample Number	LH0286715	LH0222279	
Sample Date	06 Mar 2024	28 Sep 2022	
Machine Hours	2047	1051	
Oil Hours	0	0	
Oil Changed	N/A	N/A	
Sample Status	NORMAL	NORMAL	
OIL COND	DITION		
Visc @ 40°C cSt	129	195	
**			

CONT	AMINATIO	ON		
Water	%	NEG	NEG	
Silicon	ppm	1	O <1	
Sodium	ppm	5	0 8	
Potassium	ppm	2	O 0	

WEA WEA	AR META	LS		
Iron	ppm	14	O 5	
Copper	ppm	4	O 2	
Lead	ppm	 <1	 <1	
Tin	ppm	0	O 0	
Aluminum	ppm	 <1	O 0	
Chromium	ppm	0	O 0	
Molybdenum	ppm	0 0	0	
Nickel	ppm	0	O 0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	○ <1	<1	
Vanadium	ppm	0	0	

vanadium	ppm	U	U	
ADDI	TIVES			
Calcium	ppm	13	6	
Magnesium	ppm	2	0	
Zinc	ppm	29	16	
Phosphorus	ppm	1218	472	
Barium	ppm	() <1	0	
Boron	ppm	150	2	



LIEBHERR CANADA LTD.

1015 SUTTON DRIVE
BURLINGTON, ON
CA L7L 5Z8
Contact: Steve Lehto
steve.lehto@liebherr.com

T: (905)319-9222 F: (905)319-6617

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LIEMISUnique No:5746034Signed:Wes DavisReport Date:08 Mar 2024

Contact/Location: Steve Lehto - LIEMIS

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

