# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

## LIEBHERR 111094 - Distribution Gear

Sample No: LH0274468
Oil Type: {unknown}

_ <b>_</b>					
SAMPLEINFORMATION					
	LH0274468				
Sample Number	LHU2/4400				
Sample Date	11 Mar 2024				
Machine Hours	2079				
Oil Hours	0				
Oil Changed	Not Changd				
Sample Status	NORMAL				
<b>A</b>					

GeoSolv Design/Build 120 VINYL CT 2ND FLOOR WOODBRIDGE, ON CA L4L 4A3 Contact: Service Manager

OIL CONDITION						
Visc @ 40°C	cSt	<b>97.7</b>				

T: F:

CONTAMINATION						
Water	%	NEG				
Silicon	ppm	<b>0</b> <1				
Sodium	ppm	<b></b> <1				
Potassium	ppm	<b>0</b> <1				
<b>6</b>						

### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

WEA	R METALS			
Iron	ppm	<b>9</b>	 	
Copper	ppm	<b>1</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>0</b> <1	 	
Chromium	ppm	<b>0</b>	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>0</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	0	 	

variaululli	ppiii	U				
ADDITIVES						
Calcium	ppm	16				
Magnesium	ppm	2				
Zinc	ppm	30				
Phosphorus	ppm	1205				
Barium	ppm	0				
Boron	ppm	292				

Depot:GEOWOOUnique No:5747222Signed:Wes DavisReport Date:14 Mar 2024







#### **GRAPHS**

