

## [ELG] LIEBHERR A924C 036737-1049 - Front Right Wheel Hut

Sample No: LH

Oil Type: GEAR OIL SAE 80

### SAMPLE INFORMATION

Sample Number	LH	 	
Sample Date	14 Mar 2024	 	
Machine Hours	17745	 	
Oil Hours	0	 	
Oil Changed	N/A	 	
Sample Status	NORMAL	 	

0

.

### **OIL CONDITION**

Visc @ 40°C

# cSt **84.5**

	<b>FAMINA</b>	TION		
Water	%	NEG	 	
Silicon	ppm	04	 	
Sodium	ppm	06	 	
Potassium	ppm	0 2	 	

Ä				
WEA WEA	<b>AR META</b>	LS		
Iron	ppm	<b>0</b> 301	 	
Copper	ppm	09	 	
Lead	ppm	<b>()</b> <1	 	
Tin	ppm	0 🔘	 	
Aluminum	ppm	<b>3</b>	 	
Chromium	ppm	<mark></mark> <1	 	
Molybdenum	ppm	0 🔘	 	
Nickel	ppm	<mark></mark> <1	 	
Titanium	ppm	0 (	 	
Silver	ppm	<1	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	

0

	DITIVES			
Calcium	ppm	<b>5</b> 9	 	
Magnesium	ppm	<b>3</b>	 	
Zinc	ppm	0 30	 	
Phosphorus	ppm	0 1249	 	
Barium	ppm	0 🔘	 	
Boron	ppm	0 250	 	



### ELG Canada

4375 CORPORATE DRIVE BURLINGTON, ON CA L7L 5P7 Contact: Service Manager

T: F: (905)335-9687

### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80. Please confirm. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:STR437BURUnique No:5747569Signed:Wes DavisReport Date:15 Mar 2024


Submitted By: Eric Leblond





GRAPHS

 $\odot$ 



Report Id: STR437BUR [WCAMIS] 02622450 (Generated: 03/18/2024 08:53:09) Rev: 1