# LIEBHERR

**CONSTRUCTION EQUIPMENT** 

### [ELG] LIEBHERR A924C 036737-1049 - Rear Right Wheel Hub

Sample No: LH

Oil Type: GEAR OIL SAE 80

<b>a</b>						
SAMPLE INFORMATION						
Sample Number	LH					
Sample Date	14 Mar 2024					
Machine Hours	17745					
Oil Hours	0					
Oil Changed	N/A					
Sample Status	NORMAL					
<b>A</b>						

Sample	Status		NORMAL	***	 
<b>A</b>					
	OIL CC	NDITION		7	
Visc @	40°C	cSt	<b>○</b> 87.7		 

CONT	CONTAMINATION								
Water	%	NEG							
Silicon	ppm	<b>1</b>							
Sodium	ppm	<b>2</b>							
Potassium	ppm	<b>2</b>							

WEAR METALS						
Iron	ppm	<b>41</b>				
Copper	ppm	<b>3</b>				
Lead	ppm	<b>0</b>				
Tin	ppm	<b>0</b>				
Aluminum	ppm	<b>()</b> <1				
Chromium	ppm	<b>0</b>				
Molybdenum	ppm	<b>0</b>				
Nickel	ppm	<b>0</b> <1				
Titanium	ppm	<b>0</b>				
Silver	ppm	<1				
Manganese	ppm	<b>0</b>				
Vanadium	ppm	0				

0							
ADDITIVES							
Calcium	ppm	<b>22</b>					
Magnesium	ppm	<b>0</b> <1					
Zinc	ppm	<b>10</b>					
Phosphorus	ppm	<b>1247</b>					
Barium	ppm	<b>0</b>					
Boron	ppm	<b>307</b>					



ELG Canada 4375 CORPORATE DRIVE BURLINGTON, ON CA L7L 5P7 Contact: Service Manager

T:

F: (905)335-9687

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80. Please confirm. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:STR437BURUnique No:5747572Signed:Wes DavisReport Date:15 Mar 2024

Submitted By: Eric Leblond

## LIEBHERR

CONSTRUCTION EQUIPMENT





#### **GRAPHS**

