LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 145272-1253 - Rear Right Wheel Hub

Sample No: LH

Visc @

Oil Type: GEAR OIL LS 80W90

SAMPLE INFORMATION					
Sample Number	LH	LH0250157	LH0250175		
Sample Date	14 Mar 2024	08 Sep 2023	05 Jun 2023		
Machine Hours	2004	1004	500		
Oil Hours	0	0	500		
Oil Changed	Changed	Changed	Changed		
Sample Status	NORMAL	NORMAL	NORMAL		
A					

e Status		NORMAL	NORIVIAL	NORWAL	
OIL CC	NDITION				
9 40°C	cSt	181	O 145	62.8	

CONTAMINATION						
Water	%	NEG	NEG	NEG		
Silicon	ppm	3	O 2	0 8		
Sodium	ppm	2	9	O 16		
Potassium	ppm	0 <1	O 0	O <1		

WEA	R METAL	S			
Iron	ppm	22	O 22	O 10	
Copper	ppm	○ <1	0 8	4	
Lead	ppm	0	O <1	<1	
Tin	ppm	0	0	0	
Aluminum	ppm	() <1	O <1	O 1	
Chromium	ppm	○ <1	O <1	O <1	
Molybdenum	ppm	0	0	0	
Nickel	ppm	○ <1	O 0	<1	
Titanium	ppm	0	0	<1	
Silver	ppm	0	0	3	
Manganese	ppm	() <1	O <1	2	
Vanadium	ppm	0	0	0	

ADDI	TIVES				
Calcium	ppm	9 4	832	3934	
Magnesium	ppm	2	3	11	
Zinc	ppm	27	379	1517	
Phosphorus	ppm	2426	O 1996	1303	
Barium	ppm	0	O 0	<1	
Boron	ppm	2	15	105	



Industrial Metals 550 Messier St. Winnipeg, MB CA R2J 0G5

Contact: Service Manager

Т	:
F	:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:IND550WINUnique No:5748261Signed:Wes DavisReport Date:19 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

