LIEBHERR

CONSTRUCTION EQUIPMENT

[(355228)] LIEBHERR LH60M 114198-1217 - Splitter Box

Sample No: LH0281025

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

5						
SAMP	LE INFORI	MATION				
Sample Number		LH0281025	LH0221829			
Sample Date		08 Feb 2024	08 Mar 2022			
Machine Hours		8700	1030			
Oil Hours		0	0			
Oil Changed		Changed	Changed			
Sample Status		NORMAL	NORMAL			
OIL CONDITION						
Visc @ 40°C	cSt	○ 86.5	181			

	MATI				
Water	%	NEG	NEG	 	
Silicon	ppm	0	O 1	 	
Sodium	ppm	<1	O 5	 	
Potassium	ppm	0	3	 	

(O) WE	BAFTAL	_		
₩ WEA	IR METAL	>		
Iron	ppm	8	O 10	
Copper	ppm	2	O 1	
Lead	ppm	0	O 1	
Tin	ppm	0	O 0	
Aluminum	ppm	0	O <1	
Chromium	ppm	0	0	
Molybdenum	ppm	0	O 0	
Nickel	ppm	0	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	0		
Vanadium	ppm	0	0	

Vanadium	ppm	0	0	
ADI	DITIVES			
Calcium	ppm	58	3 7	
Magnesium	ppm	0 1	O 3	
Zinc	ppm	94	○ 34	
Phosphorus	ppm	1162	2044	
Barium	ppm	0	O 2	
Boron	ppm	270	2	



AltaSteel
9401 34 St NW
Edmonton, AB
CA T6B 2X6
Contact: Richard Bailey
richard.bailey@altasteel.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:ALT940EDMUnique No:5748598Signed:Wes DavisReport Date:20 Mar 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





GRAPHS

