## **CONSTRUCTION EQUIPMENT**

## LIEBHERR R945 055572-1866 - Splitter Box

PETRO CANADA TRAXON SYNTHETIC 75W90

Sample No: LH0281035

**Oil Type:** 

## **SAMPLE INFORMATION**

Sample Number	LH0281035	LH0226579	 	
Sample Date	21 Mar 2024	06 Apr 2023	 	Am
Machine Hours	1586	562	 	116
Oil Hours	0	0	 	Sur
Oil Changed	Changed	Changed	 	CA
Sample Status	NORMAL	NORMAL	 	Cor
				т.

192

## **OIL CONDITION**

Visc @ 40°C

...

### cSt 99.2

Water	%	NEG	NEG		
Silicon	ppm	<mark></mark> <1	01		
Sodium	ppm	02	0 2		
Potassium	ppm	<mark></mark> <1	01		

Ä				
WEA	<b>R</b> META	LS		
Iron	ppm	0 11	0 13	 
Copper	ppm	<b>○</b> <1	02	 
Lead	ppm	0 (	○ <1	 
Tin	ppm	0	0	 
Aluminum	ppm	<b>○</b> <1	0	 
Chromium	ppm	0	0	 
Molybdenum	ppm	0	0	 
Nickel	ppm	0	○ <1	 
Titanium	ppm	0	0	 
Silver	ppm	0	0	 
Manganese	ppm	0	◯ <1	 
Vanadium	ppm	0	0	 

#### ٥ **ADDITIVES** Calcium 0 17 ppm 09 ○ <1 02 Magnesium ppm 0 12 Zinc 0 25 ppm 0 1560 Phosphorus ppm 0 1246 Barium 0 0 ppm Boron ○ <1 ppm 0 269





nix Recycling 698 140 Street rrey, BC V3R 2V4 ntact: Service Manager

Т: F: (250)802-1002

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	٨N
Unique No:	57
Signed:	W
Report Date:	27

MI116SUR 750136 les Davis Mar 2024

# CONSTRUCTION EQUIPMENT



GRAPHS

 $\odot$ 

