LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH60M 147037-1217 - Splitter Box

Sample No: LH0271341

Oil Type: PETRO CANADA TRAXON 75W90 SYNTHETIC

5								
Samp	ole Info	mation						
Sample Number		LH0271341	LH0131744	LH0271330				
Sample Date		02 Apr 2024	03 Feb 2024	31 Oct 2023				
Machine Hours		2572	2067	1062				
Oil Hours		0	0	0				
Oil Changed		Changed	Changed	Changed				
Sample Status		NORMAL	NORMAL	NORMAL				
Oil Co	ondition	ı						
Visc @ 40°C	cSt	90.3	107	O 141				
Contamination								
Water	%	NEG	NEG	NEG				
Silicon	ppm	0	O <1	3				
Sodium	ppm	1	O 2	3				
Potassium	ppm	○ <1	O 1	O <1				

Wed	ır Metal	s			
Iron	ppm	9	O 12	1 4	
Copper	ppm	() <1	O <1	O <1	
Lead	ppm	0	0	<1 <1	
Tin	ppm	0	O 0	O 0	
Aluminum	ppm	0	O <1	O <1	
Chromium	ppm	0	O 0	O 0	
Molybdenum	ppm	0	0	O 0	
Nickel	ppm	0	O 0	O 0	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	<1	
Manganese	ppm	0	0	O 0	
Vanadium	ppm	0	0	0	

Variadium	ppiii	U	U	O				
Addit								
Additives								
Calcium	ppm	143	O 14	O 14				
Magnesium	ppm	4	O 1	O 2				
Zinc	ppm	102	O 15	18				
Phosphorus	ppm	1200	O 1299	O 1397				
Barium	ppm	0	O 0	O <1				
Boron	ppm	254	O 227	119				



STELLA JONES INC 25 BRAID ST NEW WESTMINSTER, BC CA V3L 3P2 Contact: Richard Vogel rvogel@stella-jones.com

T: (604)999-9220 F: (604)526-8597

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:STE25NEWUnique No:5759858Signed:Wes DavisReport Date:04 Apr 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

