LIEBHERR

CONSTRUCTION EQUIPMENT



Sample No: LH0283326

Silicon

Sodium

Oil Type: SHELL ROTELLA T6 0W40

ppm

ppm

4

2

_				
U San	ple Infor	mation		
Sample Number	r	LH0283326	LH	
Sample Date		29 Mar 2024	15 Mar 2024	
Machine Hours		1174	0	
Oil Hours		0	0	
Oil Changed		Changed	N/A	
Sample Status		NORMAL	ABNORMAL	
<u> </u>				
Oil	Condition	ı		
Visc @ 40°C	cSt	79.5	48.9	
Con	taminati	on		
Water	%	NEG	NEG	

05

02

	le le	U –	<u> </u>	
Potassium	ppm	8	O 7	
**				
(O) Woo	ır Metals			
- WEG	ir Meiuis			
Iron	ppm	2	O 22	
Copper	ppm	6	O 19	
Lead	ppm	0	0	
Tin	ppm	0	O <1	
Aluminum	ppm	 <1	O <1	
Chromium	ppm	0	O 0	
Molybdenum	ppm	3	0	
Nickel	ppm	0	O 0	
Titanium	ppm	<1	<1	
Silver	ppm	0	O 0	
Manganese	ppm	0	2	
Vanadium	ppm	0	0	
THE STATE OF THE S				

vanadium	ppm	U	U					
Additives								
Calcium	ppm	2026	2028					
Magnesium	ppm	24	18					
Zinc	ppm	1100	1069					
Phosphorus	ppm	941	1040					
Barium	ppm	() <1	0					
Boron	ppm	37	64					



HUBERT & FILS 474 ROUTE 105 BOIS-FRANC, QC CA J9E 3A9 Contact: Eric Brisebois ericbrisebois99@gmail.com

T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:HUBBOIUnique No:5761050Signed:Kevin MarsonReport Date:10 Apr 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

