

## LIEBHERR LH50 086895 - Energy Recovery Cylinder

Sample No: LH

Oil Type: NOT GIVEN

#### **Sample Information**

Sample Number		LH	LH0243006		
Sample Date		22 Mar 2024	14 Jan 2023		
Machine Hours		25110	22640		
Oil Hours		0	0		
Oil Changed		Changed	Changed		
Sample Status		SEVERE	SEVERE		
<b>Oil Condition</b>					
Visc @ 40°C	cSt	88.9	89.8		
Visc @ 100°C	cSt	0 14.6			
Viscosity Index (VI)	Scale	171			
Contamination					

Contamination					
Water	%	NEG	NEG		
Particles >4µm		<b>140556</b>	73781		
Particles >6µm		<b>17067</b>	7233		
Particles >14µm		<u> </u>	63		
ISO 4406:1999 (c)		24/21/15	23/20/13		
Silicon	ppm	0 35	○ 74		
Sodium	ppm	<b>5</b>	07		
Potassium	ppm	07	0 13		

#### Wear Metals

- wec	ar merai	•		
Iron	ppm	0 142	132	 
Copper	ppm	○ <1	○ <1	 
Lead	ppm	0 🔘	◯ <1	 
Tin	ppm	0 🔘	0	 
Aluminum	ppm	0 16	0 31	 
Chromium	ppm	0 9	0 11	 
Molybdenum	ppm	0	2	 
Nickel	ppm	◯ <1	○ <1	 
Titanium	ppm	<1	2	 
Silver	ppm	0	0	 
Manganese	ppm	3	3	 
Vanadium	ppm	0	<1	 

ø

 $\bigcirc$ 

Additives					
Calcium	ppm	22	29		
Magnesium	ppm	9	19		
Zinc	ppm	17	15		
Phosphorus	ppm	302	341		
Barium	ppm	<1	0		
Boron	ppm	4	4		
DUIUII	ppiii	4	4		



LIEBHERR CANADA LTD.

10374 267 ST. ACHESON, AB CA T7X 6A2 Contact: Dustin Fluet dustin.fluet@liebherr.com T: (780)962-6088 F: (780)962-6799

### Diagnosis

Check seals and/or filters for points of contaminant entry. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. We recommend you service the filters on this component. Resample in 30-45 days to monitor this situation.All component wear rates are normal. There is a high amount of silt (particulates < 14 microns in size) present in the fluid. The fluid is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

 Depot:
 LIESPR


 Unique No:
 5761574

 Signed:
 Kevin Marson

 Report Date:
 18 Apr 2024

 Submitted By: Eric Beaulieu

4 11:44:45) Rev: 1



# **LEBHERR** CONSTRUCTION EQUIPMENT



Graphs

Ö

