# **CONSTRUCTION EQUIPMENT**

## [BLANCHARD] LIEBHERR LH22 139277 - Rear Differential

Sample No: LH0282724

Oil Type:

#### GEAR OIL SAE 75W90

LH0282724

08 Apr 2024 2161

0

N/A NORMAL

0 105

#### Sample Information

Sample Number	
Sample Date	
Machine Hours	
Oil Hours	
Oil Changed	
Sample Status	

nple Status

#### **Oil Condition**

Visc @ 40°C

. .

## cSt

	Contamination							
Wat	ter	%	NEG					
Silic	con	ppm	0					
Soc	lium	ppm	02					
Pot	assium	ppm	0 <1					

Ä				
Wea	r Metals			
Iron	ppm	<b>0</b> 10	 	
Copper	ppm	01	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	0	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>○</b> <1	 	
Vanadium	ppm	0	 	

Additives

Calcium	ppm	<b>0</b> 109			
Magnesium	ppm	0 2			
Zinc	ppm	0 47			
Phosphorus	ppm	0 1326			
Barium	ppm	0 🔘			
Boron	ppm	268			



#### LIEBHERR CANADA LTD.

1015 SUTTON DRIVE BURLINGTON, ON CA L7L 5Z8 Contact: Steve Lehto steve.lehto@liebherr.com T: (905)319-9222 F: (905)319-6617

#### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 LIEMIS

 Unique No:
 5762063

 Signed:
 Wes Davis

 Report Date:
 15 Apr 2024

 Submitted By: Eric Leblond

# **CONSTRUCTION EQUIPMENT**



Graphs

 $\odot$ 

