

LIEBHERR PR736LGP 020009-1736 - Right Final Drive

PETRO CANADA TRAXON 75W90 SYNTHETIC

Sample No: LH0286668

Oil Type:

٥

Calcium

Zinc

Barium

Magnesium

Phosphorus

Additives

ppm

ppm

ppm

ppm

ppm

Ö Sample Information						
Sample Number		LH0286668	LH0237753			
Sample Date		25 Mar 2024	22 Feb 2023			TH
Machine Hours		2903	2011			R
Oil Hours		0	0			AS
Oil Changed		Changed	Changed			C
Sample Status		NORMAL	ABNORMAL			Co
Oil Condition						T: F:
Visc @ 40°C	cSt	177	0 341			

Conte	mination			
Water	%	NEG	NEG	
Silicon	ppm	07	8	
Sodium	ppm	2	2	
Potassium	ppm	○ <1	○ <1	

Ä				
₩ee	ar Metals	;		
Iron	ppm	3 1	◯ 51	
Copper	ppm	06	0 21	
Lead	ppm	0	◯ <1	
Tin	ppm	0 (01	
Aluminum	ppm	01	2	
Chromium	ppm	0	○ <1	
Molybdenum	ppm	0	0	
Nickel	ppm	○ <1	<1	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	 <1	◯ <1	
Vanadium	ppm	0	0	

24

20

1124

 $\bigcirc 2$

0 17



HOMAS CAVANAGH CONSTRUCTION LTD R # 2, 9094 CAVANAGH ROAD SHTON. ON CA K0A 1B0 Contact: Keith

: (613)257-4995 : (613)253-0071

Diagnosis

Confirm the source of the lubricant being utilized for top-up/fill. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. Additive levels indicate the addition of a different brand, or type of oil. The condition of the oil is acceptable for the time in service.

Depot:	CAV
Unique No:	5762
Signed:	Wes
Report Date:	17 A

VASH 2840 s Davis Apr 2024 Submitted By: ?

0 11

02

011

02


1882





Graphs

 \odot



Report Id: CAVASH [WCAMIS] 02629708 (Generated: 07/02/2024 13:11:44) Rev: 1