## **CONSTRUCTION EQUIPMENT**

## LIEBHERR R936LC 048600-1490 - Right Final Drive

Sample No: LH0288281

Oil Type: LIEBHERR SYNTOGEAR PLUS 75W-90

## **Sample Information** LH0288281 Sample Number LH0177986 LH0162701 Sample Date 15 Apr 2024 27 Oct 2020 31 Jan 2020 Machine Hours 2927 1027 501 **Oil Hours** 0 0 0 Oil Changed Not Changd Changed Changed NORMAL Sample Status NORMAL NORMAL **Oil Condition** Visc @ 40°C cSt 0 106 194 0 196 **Contamination** % Water NEG NEG NEG Silicon 10 8 ppm 0 11 0 Sodium 04 05 03 ppm Potassium ppm 01 03 Wear Metals

		•			
Iron	ppm	08 (	0 43	65	
Copper	ppm	0 (	○ <1	○ <1	
Lead	ppm	0 🔘	0	0	
Tin	ppm	0 🔘	0	0	
Aluminum	ppm	03	3	3	
Chromium	ppm	<mark></mark> <1	○ <1	01	
Molybdenum	ppm	0 🔘	○ <1	◯ <1	
Nickel	ppm	0 2	<1	<1	
Titanium	ppm	0	<1	<1	
Silver	ppm	0	<1	0	
Manganese	ppm	<b>○</b> <1	○ <1	◯ <1	
Vanadium	ppm	0	<1	<1	

	itives				
Calcium	ppm	9	6	0 10	
Magnesium	ppm	0 2	○ <1	○ <1	
Zinc	ppm	<b>0</b> 15	0 10	0 10	
Phosphorus	ppm	0 1482	2216	2166	
Barium	ppm	<b>3</b>	0 4	9	
Boron	ppm	0 228	03	6	



COLOURED AGGREGATES INC.

158 DON HILLOCK DRIVE,, UNIT 12-13 AURORA, ON CA L4G 0H6 Contact: Jeff Oravecz Jeff@colouredaggregates.com T: (416)491-0230 F:

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 COL158AUR

 Unique No:
 5762846

 Signed:
 Wes Davis

 Report Date:
 17 Apr 2024





Ø

Graphs

