LIEBHERR

CONSTRUCTION EQUIPMENT

LIEBHERR LH30M 090077 - Transmission

Sample No: LH0276291

Oil Type: PETRO CANADA 10W40

Sample Information						
Sample Number	LH0276291	LH				
Sample Date	16 Apr 2024	05 Jan 2022				
Machine Hours	6756	5072				
Oil Hours	0	0				
Oil Changed	Changed	Changed				
Sample Status	NORMAL	ABNORMAL				
A						

Sample Status		NORMAL	ABNORMAL	
Oil Co	ndition			
Visc @ 40°C	cSt	63.6	63.9	
Conta	mination			

Cont	aminati	on			
Water	%	NEG	NEG	 	
Silicon	ppm	2	O 4	 	
Sodium	ppm	3	O 7	 	
Potassium	ppm	0	O 1	 	

10				
Wea	r Metals			
Iron	ppm	10	O 16	
Copper	ppm	13	O 19	
Lead	ppm	0	O <1	
Tin	ppm	O <1	O <1	
Aluminum	ppm	 <1	O 1	
Chromium	ppm	0	O <1	
Molybdenum	ppm	61	S 58	
Nickel	ppm	0	O <1	
Titanium	ppm	0	0	
Silver	ppm	0	<1	
Manganese	ppm	5	7	
Vanadium	ppm	0	0	

vanadium	ppm	U	U	
Addi	tives			
Calcium	ppm	1154	O 1302	
Magnesium	ppm	1003	O 964	
Zinc	ppm	1222	O 1248	
Phosphorus	ppm	1076	O 1159	
Barium	ppm	0	O <1	
Boron	ppm	6	0 2	



ELG Canada 4375 CORPORATE DRIVE BURLINGTON, ON CA L7L 5P7 Contact: Service Manager

T:

F: (905)335-9687

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:STR437BURUnique No:5762919Signed:Kevin MarsonReport Date:18 Apr 2024

LIEBHERR

CONSTRUCTION EQUIPMENT





Graphs

